


PHOTO VIEW



- NOTES:  
 1: 1ST LAMINATE MADE FROM ACRYLIC SHEET.  
 2: REINFORCED BY GLASS AND POLYESTER COMPOSITE  
 3: BOTTOM REINFORCED WITH WOOD TO MEET 300# LOAD TEST.  
 4: 2ND LAMINATE COVERS ALL REINFORCEMENTS PLUS .100" ADDED TO UNREINFORCED AREAS.

UNIT PART NUMBERS		UNLESS OTHERWISE SPECIFIED TOLERANCES ARE AS FOLLOWS		<b>Fiber Care Baths, Inc.</b>			9832 Yucca Rd. Adelanto, CA 92301 Phone: 760-246-0019 Fax: 760-246-5189		
RIGHT HAND UNIT	<b>APR42-36</b>	DECIMAL: .XX = ±.010 .XXX = ±.005	FRACTIONAL: ±1/8" ANGULAR: ±1/2°				TITLE <b>ACRYLIC SHOWER PAN, 3-WALL</b>		
LEFT HAND UNIT	<b>APR42-36</b>	CAPACITY/ OPERATING LEVEL:		GAL	DATE 12/05/07 SCALE <b>NTS</b> PAGE 1 OF 1				
<small>THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF FIBER CARE BATHS, INC. ANY REPRODUCTION OR UNAUTHORIZED USE IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF FIBER CARE BATHS, INC. IS STRICTLY PROHIBITED. PRODUCT CONFIGURATION, DIMENSIONS, STANDARD ACCESSORIES, MATERIALS COMPOSITION AND CONSTRUCTION ARE SUBJECT TO CHANGE WITHOUT NOTICE.</small>		CAPACITY/ OVERFLOW LEVEL:		GAL				DATE 12/05/07 SCALE <b>NTS</b> PAGE 1 OF 1	
		APPROX. UNIT WEIGHT:		LBS					
		APPROX. SHIPPING WEIGHT:		LBS					